COLD WEATHER MODIFICATION

TSP8CYL-1045-115
ENGINE PREHEAT KIT, 115 VOLT
FOR
8 CYLINDER
720 SERIES LYCOMING ENGINES
(REPLACES TAS100-19)

INCLUDES THE FOLLOWING CHECKED [✓] ITEMS:

DOCUMENTS:

	QTY	ITEM NUMBER	DESCRIPTION
[ ]	1	02813	CABLE KIT - WIRE DIAGRAM
[ ]	1	TFMS1045	FLIGHT MANUAL SUPPLEMENT - OPERATION
[ ]	1	TICA1045	INSTRUCTION FOR CONTINUED AIRWORTHINESS
[ ]	1	TLB0001	LOGBOOK ENTRY - STICKER
[ ]	1	TN02771	INSTRUCTION - THREADED ELEMENT
[ ]	1	TN02788	INSTRUCTION - BONDING
[ ]	1	TNP1045	INSTRUCTION - PREHEAT INSTALLATION
[ ]	1	TWC0001	REGISTRATION / WARRANTY CARD

COMPONENTS:

	QTY	ITEM NUMBER	DESCRIPTION
[ ]	1	AN900-16	CRUSH WASHER - SUMP ELEMENT
[ ]	3	CB911	SOLVENT WIPE
[ ]	1	CB92	CLICK BOND INSTALLATION KIT
[ ]	1	TC02813	CABLE KIT
[ ]	3	TEP2650-115/120	PAD HEAT ELEMENT: 1-FRONT LOWER CASE, 1-LEFT SUMP, 1-RIGHT SUMP
[ ]	1	TP02770-115	SHORE POWER PLUG - 115 VOLT
[ ]	1	TTP2634-115/50	SUMP SCREEN ELEMENT
[ ]	8	TTP2771-115/50	THREADED HEAT ELEMENT - ONE EACH CYLINDER ASSEMBLY
[ ]	1	TU02615-115	PLACARD - 115 VOLT
[ ]	3	TU02782	CLICK BOND CABLE MOUNT (CB9120)
[ ]	80	TU02847	CABLE TIE - 8", BLACK

COPY

- MODIFICATION AND SUBSTITUTIONS WITH ENGINEERING APPROVAL.
- SOURCED SEPARATELY: CONSUMABLES, MOUNTING HARDWARE AND
  APPROVED ELEMENT BONDING SEALANT (REQUIRED FOR INSTALLATION NOT SUPPLIED DUE TO EXPIRATION DATE)
  REFERENCE, TNP1045 INSTRUCTION - PREHEAT INSTALLATION

CHANGE	TYPE	REV	INT	DATE
	REV APPROVAL		Dirk Ellis	
SPLIT VOLTAGES 2771 THREADED ELEMTENTS		D	DNE	APR-30-2013
REFORMAT, UPDATE TO -DT SYSTEM		C	GDO	JAN-26-2011
ADD TAS104 & TAS403,		B	PGT	JUN-24-1998
NOTE- WASHER TYPE TCOUPLE		A	PGT	MAY-12-1997

TANIS AIRCRAFT PRODUCTS
GLENWOOD MUNICIPAL AIRPORT
GLENWOOD, MN 56334 USA
+1.952.224.4425

TITLE: ENGINE PREHEAT KIT

DRAWN BY:	PGT	MAY-12-1997
CHECKED BY:	PGT	MAY-12-1987
SCALE:	N/A	(.xlsx format B)

SPEC: N/A
SUPERSEDES: N/A
SHEET 1 OF 1
DWG: 1045-115