





PO Box 117, 18781 County Rd 22
Glenwood MN, 56334
320-634-4772; 800-443-2136
www.Tanisaircraft.com

Instruction TN02651

TE02651 Pad Heat Element

Continental 520/550 series engines with the top tuned induction systems are very crowded in the standard location for installing the heat element on the top of the crankcase. Although the standard pad will fit in the standard location, the induction tubes must be detached to assure a good installation. The TE02651 is designed to fit toward the front of the case on the dome shaped part very conveniently. Follow the standard cleaning and installation instructions for the general procedure. See the photos below for placement of the element. Typical engine styles affected: IO-550-G, N, P, R and TSIO-550B, C, E. Is similar to a TANIS TAS300B pad element.

Location of TE02651 on
Top of Crankcase



Tanis Aircraft Products PO Box 117 Glenwood, MN 56334
1-800-443-2136 (US & Canada) www.tanisaircraft.com

Rev: 09/24/2010 GDO
APPROVAL: _____